# Supplier Quality Requirements Q8000

- Scope
  - > Produce Facilities





## SUPPLIER QUALITY ASSURANCE REQUIREMENTS

Doc. Group SQAR

Doc. No. Q8000

Rev. No.	Date	Description	Prepare	Review	Approval
0	2014.10.27	Initial Issue	NI Kim	SW Kim	YH Cho



### SUPPLIER QUALITY ASSURANCE REQUIREMENTS

Doc. No.	Q8000		
Pages	1 OF 1		
Rev. No.	0		
Rev. Date	2014. 10. 27		

#### 1. Purpose

This requirements specifies quality assurance requirements for production facility that are purchased order/contacted suppliers of Hanwha Corporation Aerospace Division(hereafter "Hanwha").

#### 2. Scope

- 2.1 This requirements applies to the Suppliers and the subtiers of the suppliers when stated on the contracts or purchase orders.
- 2.2 Relations to other requirements
  - Suppliers shall meet all the requirements on the contract and are responsible for providing the relevant products and services to Hanwha. If the requirements on the contract do not conform to the this SQAR the priority shall be given to the requirements of the contract.
- 2.3 If the requirements on this SQAR cannot be met, the suppliers must notify Hanwha and discuss prior to signing the contracts and receiving the purchase orders.
- 2.4 Suppliers shall refer to the latest revision of this requirements. When the manufacturing cost increases as a result of revision of the requirements, the suppliers must notify Hanwha's purchasing department for discussion.

#### 3. Quality Assurance Requirements

- 3.1 Production facility suppliers shall deliver products which conform to the specifications on the final estimate, and documents shall be attached to prove the fact.
- 3.2 Production facilities shall be inspected by Hanwha prior to delivery. Or the inspection can take place after delivery only if agreement was previously made through discussion with Hanwha.
- 3.3 In case of precision machining facilities, a run-up test shall be carried out after installing the facilities, and documented test reports shall be submitted to Hanwha.